

SSM 49167 - 2020 Transit - High Current Battery Junction Box - Master Fuse Replacement

Some 2020 Transit vehicles may exhibit an open master fuse in the high current battery junction box. The master fuses are now available as a separate service part and can be replaced without replacing the high current battery junction box or wiring harness. Tighten M8 nuts to 12 +/- 1.8 Nm (106 +/- 16 lb-in). Tighten M5 nuts to 5.4 +/- .9 Nm (48 +/- 8 lb-in).

APPLICABLE VEHICLES
2020 TRUCK: TH V363N TRANSIT